

# General Environmental Incident Summary

**Incident:** 3957      **Date/Time Notice:** 11/4/2015      1434      **DEM Incident No:**  
**Responsible Party:** Hofmann Trucking  
**Date Incident:** 11/3/2015      **Time Incident:** 1525      **Duration:** 2 minutes  
**County:** McKenzie      **Twp:** 148      **Rng:** 105      **Sec:** 36      **Qtr:**  
**Lat:** 47.59249      **Long:** -103.99920      **Method:** Interpolation from map  
**Location Description:** ONEOK Grasslands Plant, 16001 Beenie Peer Road Sidney Montana 59270

**Submitted By:** Byron Skaley      **Affiliation:** ONEOK Employee  
**Address:** 2700 Lincoln Ave SE  
**City:** Sidney      **State:** MT      **Zip:** 59270

## Received By:

**Contact Person:** Chris Mack  
8060 36th ST SE  
Jamestown, ND 58401

**Distance Nearest Occupied Building:** 200 Feet      **Release Contained:** Yes

**Type of Incident:** Hydraulic hose broke on transport truck

**Description of Released Contaminant:** Hydraulic hose fluid

**Volume Spilled:** 3.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

during truck loading a hydraulic hose broke and release 3 gallons of fluid on the ground.

## Risk Evaluation:

No Immediate Risk Evaluation

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

No Potential Environmental Impacts

## Action Taken or Planned:

Hydraulic fluid and soil was remediated

## Wastes Disposal Location:

## Agencies Involved:

## **Updates**

---

**Date:** 11/9/2015    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

According to the report, 1 barrel of water was released during the drilling of a pipeline. Follow up when in the vicinity inspecting other reported releases due to the same cause and the same pipeline ROW.

---

**Date:** 12/17/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Cooper, Mike

**Updated Volume:**

**Notes:**

Arrived on site at 1:45 p.m. 23 degrees, wind 5-10 mph SE. According to the report, spill happened at a transload facility while offloading. Photos taken of site. Site has been cleaned since incident, and no visible contamination was present at time of inspection. Spill happened on industrial site.

NDIC retains oversight.